U.S. DEPARTMENT OF LABOR Occupational Safety and Health Administration

Form Approved OMB No. 44-R1387

MATERIAL SAFETY DATA SHEET

Required under USDL Safety and Health Regulations for Ship Repairing, Shipbuilding, and Shipbreaking. (29 CFR 1915, 1916, 1917)

Shipbuilding, and Shipbreaking (29 CFR 1915, 1916, 1917)						
SECTION I						
MANUFACTURER'S NAME Dexter Corporation, Hysol Division		EMERGENCY TELEPHONE 415/687-4201	NO.			
ADDRESS (Number, Street, City, State, and ZIP Code) 2850 Willow Pass Road (P.O. Box 312), Pittsburg, California 94565						
CHEMICAL NAME AND SYNONYMS : TRADE NAME AND SYNONYMS						
CHEMICAL FAMILY Polyamide/Aliphatic Amine	FORMU	A				
SECTION II - INGREDIENTS						
	- INCHEDIENTS					
PAINTS, PRESERVATIVES, & SOLVENTS	None of th	- America 19 1 - 7 - 1 - 1 - 1 - 1		:		
None of the ingredients listed constitute						
CATALYST Polyamide	a hazardous ingredient as defined by Federal OSHA in 29CFR 1910 or Cal/OSHA in "The Director's List of Hazardous Substances", except Diethylenetriamine					
Diethylenetriamine						
SOLVENTS						
ADDITIVES						
OTHERS						
HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES						
This material is D.O.T. restricted.						
"Alkaline Corrosive Liquid N.O.S."						
(Diethylenetriamine).						

	SECT	ION III - F	PHYSICAL DATA	•	
BOILING POINT (°F.) Deco	mposes before	boiling	SPECIFIC GRAVITY (H2	O=1)	0.96
VAPOR PRESSURE (mm Hg.)	Not Determin	ed	PERCENT, VOLATILE BY VOLUME (%)	Not Determined	
VAPOR DENSITY (AIR=1)	Not Determin	ed	EVAPORATION RATE	Not Determined	
SOLUBILITY IN WATER	Slightly'				
APPEARANCE AND ODOR	Amber liquic	l with amm	onical odor		

• SECTION IV - FIRE AND EXPLOSION HAZARD DATA .							
FLASH POINT (Method used) >200°F TCC		FLAMMABLE LIMITS	Lei	Uel			
Chemical Foam, dry chemicals, CO2. Water Spray							
SPECIAL FIRE FIGHTING PROCEDURES Wear self-contained breathing apparatus when							
fighting fires in confined areas.							
UNUSUAL FIRE AND EXPLOSION HAZARDS	Dense smo	oke may be liberated	•				
•.				•			

SECTION V - HEALTH HAZARD DATA

Corrosive to skin and eyes. Can cause chemical burns to skin and severe chemical burns to eyes. Vapors irritating and may cause chest discomfort and bronchitis symptoms. Moderately toxic by ingestion. Give water or milk if swallowed, do not induce vomiting. Get medical help. Skin contact - flush with water. Then wash thourghly with soap and water. Eye contact - flush with water immediately 15 minutes and get medical help.

			SECTIO	N VI -	REACTIVITY DATA
STABILITY	TABILITY UNSTABLE		CONDITIONS TO AVOID		
STABLE		χ			
Strong oxidizing agents, strong Lewis or mineral acids.					
HAZARDOUS DE	COMPOS	ITION PRODUC	co,	NOx, a	Idehydes, acids and undetermined organics.
HAZARDOUS MAY OCCUR POLYMERIZATION WILL NOT OCC			Х	Do not mix with resins in quanities greater	
		WILL NOT O	CCUR		than one pound or excessive and irreversibl
					heat build-up may occur.

SECTION VII - SPILL OR LEAK PROCEDURES					
STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED					
Wear protective clothing, gloves and safety glasses. Cover with absorbent					
<u>wear protective clothing, gloves and safety glasses</u> . Cover with absorbent					
develop diverse. Cover with absorbett					
material then Course up and the C					
material, then Scrape up and transfer to metal container. Flush remaining					
· · · · · · · · · · · · · · · · · · ·					
residue with water.					
WASTE DISPOSAL METHOD					
Dispose of as hazandous waste according to D.O.T. Land.					
Dispose of as hazardous waste according to D.O.T. hazard class. If not regulated					
DV D.O.T., dispose of as OPM-E. Disposal method can be lead busined as a lead busine					
by D.O.T., dispose of as ORM-E. Disposal method can be land burial or chemical					
incineration as regulated by all governmental agencies.					
agencies.					

SECTION VIII - SPECIAL PROTECTION INFORMATION					
RESPIRATORY PRO	otection (Specify type) air line or self-contained wh	en working ir	confined areas		
VENTILATION	Recommended when applying or curing.		SPECIAL		
	MECHANICAL (General) Recommended	OTHER			
Impervious plastic or rubber EYE PRO		EYE PROTECTION Safet	ty glasses or goggles		
As needed to protect skin and clothing					

OF OTHER WAR ARE A STATE OF THE	
SECTION IX - SPECIAL PRECAUTIONS	
PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING	
Keep product cool in accordance with label instructions.	
other precautions Follow recommended curing schedule.	
ANSI Class 4&5	

PAGE (2)

Updated: 01 Feb 84

Updated by:__

Form OSHA-20